

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

IM1218  
NW  
> 1  
1.583 mi.  
8358 ft.

EXXON COMPANY USA  
8779 BAY PARKWAY  
BROOKLYN, NY 11214

NY LTANKS  
NY Spills  
NY MANIFEST

S109826759  
N/A

Site 3 of 3 in cluster IM

Relative:  
Higher

Actual:  
20 ft.

LTANKS:

Name: EXXONMOBIL S/S  
Address: 8775 BAY PARKWAY  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 9100451 / 1992-03-25  
Facility ID: 9100451  
Site ID: 297828  
Spill Date: 1991-04-10  
Spill Cause: Tank Test Failure  
Spill Source: Gasoline Station or other PBS Facility  
Spill Class: B3  
Cleanup Ceased: 1992-03-25  
SWIS: 2401  
Investigator: LEE  
Referred To: Not reported  
Reported to Dept: 1991-04-11  
CID: Not reported  
Water Affected: Not reported  
Spill Notifier: Tank Tester  
Last Inspection: Not reported  
Recommended Penalty: False  
Meets Standard: True  
UST Involvement: True  
Remediation Phase: 0  
Date Entered In Computer: 1991-04-17  
Spill Record Last Update: 2004-03-01  
Spiller Name: Not reported  
Spiller Company: EXXONMOBIL  
Spiller Address: Not reported  
Spiller County: 001  
Spiller Contact: Not reported  
Spiller Phone: Not reported  
Spiller Extention: Not reported  
DEC Region: 2  
DER Facility ID: 240961  
DEC Memo: ""  
Remarks: "(4) 550 GAL TANKS,SYSTEM TEST,FAILED PETRO TITE WITH A LEAK RATE OF  
-.230GPH,UNKNOWN ACTION."

All TTF:

Facility ID: 9100451  
Spill Number: 9100451  
Spill Tank Test: 1538443  
Site ID: 297828  
Tank Number: Not reported  
Tank Size: 0  
Material: 0009  
EPA UST: Not reported  
UST: Not reported  
Cause: Not reported  
Source: Not reported  
Test Method: 00  
Test Method 2: Unknown  
Leak Rate: .00

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Gross Fail: Not reported  
Modified By: Spills  
Last Modified Date: Not reported

All Materials:

Site ID: 297828  
Operable Unit ID: 953995  
Operable Unit: 01  
Material ID: 426647  
Material Code: 0009  
Material Name: gasoline  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: .00  
Units: G  
Recovered: .00  
Oxygenate: Not reported

Name: EXXON #3-37337  
Address: 8775 BAY PARKWAY  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 9705695 / 2003-10-15  
Facility ID: 9705695  
Site ID: 297829  
Spill Date: 1997-08-11  
Spill Cause: Tank Failure  
Spill Source: Gasoline Station or other PBS Facility  
Spill Class: B3  
Cleanup Ceased: Not reported  
SWIS: 2401  
Investigator: LEE  
Referred To: Not reported  
Reported to Dept: 1997-08-11  
CID: 297  
Water Affected: Not reported  
Spill Notifier: Other  
Last Inspection: Not reported  
Recommended Penalty: False  
Meets Standard: False  
UST Involvement: False  
Remediation Phase: 0  
Date Entered In Computer: 1997-08-11  
Spill Record Last Update: 2003-10-15  
Spiller Name: MELISSA WINSOR  
Spiller Company: EXXONMOBIL  
Spiller Address: 3225 GALLOWES ROAD  
Spiller County: 001  
Spiller Contact: MATT SMITH  
Spiller Phone: Not reported  
Spiller Extention: Not reported  
DEC Region: 2  
DER Facility ID: 240961  
DEC Memo: ""  
Remarks: "CALLER STATES THAT SOIL AND P-GRAVEL CONTAMATED WITH FUEL OIL  
SPILLED OVER THE FILL TUBE OF THE TANKS ON THE PREMISES OF A CLOSED  
EXXON STATION - APPROX 10 YARDS OF CONTAMINATED SOIL HAS BEEN REMOVED"  
Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

All Materials:

Site ID: 297829  
Operable Unit ID: 1049053  
Operable Unit: 01  
Material ID: 331324  
Material Code: 0001A  
Material Name: #2 fuel oil  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: .00  
Units: G  
Recovered: .00  
Oxygenate: Not reported

Name: EXXONMOBIL S/S  
Address: 8775 BAY PARKWAY  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 9108911 / 1992-03-25  
Facility ID: 9108911  
Site ID: 219633  
Spill Date: 1991-11-20  
Spill Cause: Tank Failure  
Spill Source: Gasoline Station or other PBS Facility  
Spill Class: B3  
Cleanup Ceased: 1992-03-25  
SWIS: 2401  
Investigator: LEE  
Referred To: Not reported  
Reported to Dept: 1991-11-20  
CID: Not reported  
Water Affected: Not reported  
Spill Notifier: Responsible Party  
Last Inspection: Not reported  
Recommended Penalty: False  
Meets Standard: True  
UST Involvement: True  
Remediation Phase: 0  
Date Entered In Computer: 1991-11-26  
Spill Record Last Update: 2003-09-12  
Spiller Name: Not reported  
Spiller Company: ExxonMobil  
Spiller Address: Not reported  
Spiller County: 999  
Spiller Contact: Not reported  
Spiller Phone: Not reported  
Spiller Extention: Not reported  
DEC Region: 2  
DER Facility ID: 240961  
DEC Memo: ""  
Remarks: ""

All Materials:

Site ID: 219633  
Operable Unit ID: 962955  
Operable Unit: 01  
Material ID: 559102  
Material Code: 0009  
Material Name: gasoline  
Case No.: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Material FA: Petroleum  
Quantity: .00  
Units: G  
Recovered: .00  
Oxygenate: Not reported

SPILLS:

Name: CUMBERLAND FARMS # 70225  
Address: 8775 BAY PARKWAY  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0906050 / 2009-08-27  
Facility ID: 0906050  
Facility Type: ER  
DER Facility ID: 240961  
Site ID: 418346  
DEC Region: 2  
Spill Cause: Other  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2009-08-24  
Investigator: HRAHMED  
Referred To: Not reported  
Reported to Dept: 2009-08-24  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Gasoline Station or other PBS Facility  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2009-08-24  
Spill Record Last Update: 2009-08-27  
Spiller Name: MELISSA GLIDDEN  
Spiller Company: CUMBERLAND FARMS # 70225  
Spiller Address: 8775 BAY PARKWAY  
Spiller Company: 999  
Contact Name: MELISSA GLIDDEN  
DEC Memo: "08/27/09-HRAHMED-Non-petroleum spill. This case is closed."  
Remarks: "WATER IN THE FILLS PUMP OUT WILL BE DONE BY PHOENIX."

All Materials:

Site ID: 418346  
Operable Unit ID: 1174533  
Operable Unit: 01  
Material ID: 2166897  
Material Code: 9999  
Material Name: other - WATER  
Case No.: Not reported  
Material FA: Other  
Quantity: Not reported  
Units: G  
Recovered: Not reported  
Oxygenate: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Name: GULF GAS 70225  
Address: 8775 BAY PARKWAY  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0911086 / 2010-01-14  
Facility ID: 0911086  
Facility Type: ER  
DER Facility ID: 240961  
Site ID: 423869  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2010-01-14  
Investigator: HRAHMED  
Referred To: Not reported  
Reported to Dept: 2010-01-14  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Gasoline Station or other PBS Facility  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2010-01-14  
Spill Record Last Update: 2010-01-14  
Spiller Name: Not reported  
Spiller Company: GULF GAS 70225  
Spiller Address: Not reported  
Spiller Company: 999  
Contact Name: MELISSA GLIDDEN  
DEC Memo: "01/14/10-HRAHMED-Non petroleum spill. Spill closed. "  
Remarks: "water in fill port/phoenix enviro will pump out"

All Materials:

Site ID: 423869  
Operable Unit ID: 1179671  
Operable Unit: 01  
Material ID: 2173442  
Material Code: 9999  
Material Name: other - water  
Case No.: Not reported  
Material FA: Other  
Quantity: Not reported  
Units: G  
Recovered: Not reported  
Oxygenate: Not reported

Name: GULF GAS STATION  
Address: 8775 BAY PARK WAY  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 1214657 / 2013-01-29  
Facility ID: 1214657  
Facility Type: ER  
DER Facility ID: 433216  
Site ID: 477911  
DEC Region: 2

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Spill Cause: Traffic Accident  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2013-01-16  
Investigator: SMSANGES  
Referred To: Not reported  
Reported to Dept: 2013-01-16  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Gasoline Station or other PBS Facility  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2013-01-16  
Spill Record Last Update: 2013-01-29  
Spiller Name: Not reported  
Spiller Company: CAR ACCIDENT  
Spiller Address: Not reported  
Spiller Company: 999  
Contact Name: FF ZAZCYK  
DEC Memo: "minor accident at a gas station. Fire Dept on site."  
Remarks: "cleanup pending"

All Materials:

Site ID: 477911  
Operable Unit ID: 1227704  
Operable Unit: 01  
Material ID: 2225193  
Material Code: 0009  
Material Name: gasoline  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 2.00  
Units: G  
Recovered: Not reported  
Oxygenate: Not reported

Name: CUMBERLAND FARMS # 70225  
Address: 8775 BAY PARKWAY  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0903223 / 2009-07-08  
Facility ID: 0903223  
Facility Type: ER  
DER Facility ID: 240961  
Site ID: 415321  
DEC Region: 2  
Spill Cause: Other  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2009-06-18  
Investigator: HRAHMED  
Referred To: Not reported  
Reported to Dept: 2009-06-18  
CID: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Water Affected: Not reported  
Spill Source: Gasoline Station or other PBS Facility  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2009-06-18  
Spill Record Last Update: 2009-07-08  
Spiller Name: MELISSA GLIDDEN  
Spiller Company: CUMBERLAND FARMS # 70225  
Spiller Address: 8775 BAY PARKWAY  
Spiller Company: 999  
Contact Name: MELISSA GLIDDEN  
DEC Memo: "07/08/09-HRAHMED-Non-petroleum related spill. This case is closed. "  
Remarks: "WATER IN THE SUMP PUMP OUT WILL BE DONE BY PHOENIX."

All Materials:

Site ID: 415321  
Operable Unit ID: 1171664  
Operable Unit: 01  
Material ID: 2163483  
Material Code: 9999  
Material Name: other - WATER  
Case No.: Not reported  
Material FA: Other  
Quantity: Not reported  
Units: G  
Recovered: Not reported  
Oxygenate: Not reported

Name: CUMBERLAND FARMS # 70225  
Address: 8775 BAY PARKWAY  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0903751 / 2009-07-08  
Facility ID: 0903751  
Facility Type: ER  
DER Facility ID: 240961  
Site ID: 415874  
DEC Region: 2  
Spill Cause: Other  
Spill Class: Not reported  
SWIS: 2401  
Spill Date: 2009-06-30  
Investigator: HRAHMED  
Referred To: Not reported  
Reported to Dept: 2009-06-30  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Gasoline Station or other PBS Facility  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Date Entered In Computer: 2009-06-30  
Spill Record Last Update: 2009-07-08  
Spiller Name: MELISSA GLIDDEN  
Spiller Company: CUMBERLAND FARMS # 70225  
Spiller Address: 8775 BAY PARKWAY  
Spiller Company: 999  
Contact Name: MELISSA GLIDDEN  
DEC Memo: "07/08/09-HRAHMED-Non-petroleum related spill. This case is closed. "  
Remarks: "WATER IN THE SUMP PUMP OUT WILL BE DONE BY PHOENIX."

All Materials:

Site ID: 415874  
Operable Unit ID: 1172200  
Operable Unit: 01  
Material ID: 2164063  
Material Code: 9999  
Material Name: other - WATER  
Case No.: Not reported  
Material FA: Other  
Quantity: Not reported  
Units: G  
Recovered: Not reported  
Oxygenate: Not reported

Name: CUMBERLAND FARMS # 70225  
Address: 8775 BAY PKWY  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0905148 / 2009-08-14  
Facility ID: 0905148  
Facility Type: ER  
DER Facility ID: 366518  
Site ID: 417400  
DEC Region: 2  
Spill Cause: Other  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2009-08-03  
Investigator: HRAHMED  
Referred To: Not reported  
Reported to Dept: 2009-08-03  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Gasoline Station or other PBS Facility  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2009-08-03  
Spill Record Last Update: 2009-08-14  
Spiller Name: MELISSA GLIDDEN  
Spiller Company: CUMBERLAND FARMS # 70225  
Spiller Address: 8775 BAY PKWY  
Spiller Company: 999  
Contact Name: MELISSA GLIDDEN  
DEC Memo: "08/14/09-HRAHMED-Non-petroleum release. This case is closed. "  
Remarks: "WATER IN THE SUMP PUMP OUT WILL BE DONE BY PHOENIX."



Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

All Materials:

Site ID: 417400  
Operable Unit ID: 1173616  
Operable Unit: 01  
Material ID: 2165569  
Material Code: 9999  
Material Name: other - WATER  
Case No.: Not reported  
Material FA: Other  
Quantity: Not reported  
Units: G  
Recovered: Not reported  
Oxygenate: Not reported

Name: CUMBERLAND FARMS 70225  
Address: 8775 BAY PARKWAY  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0913102 / 2010-03-19  
Facility ID: 0913102  
Facility Type: ER  
DER Facility ID: 240961  
Site ID: 426022  
DEC Region: 2  
Spill Cause: Human Error  
Spill Class: Not reported  
SWIS: 2401  
Spill Date: 2010-03-16  
Investigator: HRAHMED  
Referred To: Not reported  
Reported to Dept: 2010-03-16  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Gasoline Station or other PBS Facility  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2010-03-16  
Spill Record Last Update: 2010-03-19  
Spiller Name: Not reported  
Spiller Company: UNK  
Spiller Address: Not reported  
Spiller Company: 999  
Contact Name: MELISSA GLIDDEN  
DEC Memo: "03/19/10-HRAHMED-Non-petroleum spill, water in the sump, weather related. This case is closed."  
Remarks: "Cleanup pending"

All Materials:

Site ID: 426022  
Operable Unit ID: 1181725  
Operable Unit: 01  
Material ID: 2175853  
Material Code: 9999  
Material Name: other - Water in Spill Bucket  
Case No.: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Material FA: Other  
Quantity: Not reported  
Units: Not reported  
Recovered: Not reported  
Oxygenate: Not reported

Name: EXXON MOBIL #37337  
Address: 8775 BAY PARKWAY  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0204461 / 2014-04-25  
Facility ID: 0204461  
Facility Type: ER  
DER Facility ID: 240961  
Site ID: 297827  
DEC Region: 2  
Spill Cause: Equipment Failure  
Spill Class: C3  
SWIS: 2401  
Spill Date: 2000-02-16  
Investigator: RSLEE  
Referred To: RD PLN STRT DATE, 4/30/06  
Reported to Dept: 2002-07-29  
CID: 205  
Water Affected: Not reported  
Spill Source: Gasoline Station or other PBS Facility  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: True  
Remediation Phase: 0  
Date Entered In Computer: 2002-07-29  
Spill Record Last Update: 2014-04-25  
Spiller Name: CALLER  
Spiller Company: EXXON MOBIL #37337  
Spiller Address: 8775 BAY PARKWAY  
Spiller Company: 001  
Contact Name: CALLER  
DEC Memo:

"04/16/09 - Comments on the January 14, 2009 Groundwater Monitoring Report were sent to Cumberland Farms on January 28, 2009. 05/06/10 - A July 1, 2009 Spill Closure Request submitted by the consultant for Cumberland Farms, Inc. (Environmental Compliance Services, Inc.) was denied by the Department in a letter dated July 28, 2009. The Department requested that another round of groundwater samples be collected from select wells to confirm that BTEX concentrations remain below 500 ppb before the Department will reconsider the spill closure request. Cumberland Farms agreed to the Department's request, and the wells were re-sampled on August 14, 2009. A follow-up Spill Closure Request, dated December 1, 2009, was denied by the Department in a letter dated December 21, 2009, due to improper sample handling procedures which invalidated the reliability of the analytical results. The Department recommended that Cumberland Farms, Inc. re-submit their spill closure request after re-sampling the affected wells utilizing proper sample handling procedures. To date, Cumberland Farms has not re-submitted their spill closure request. 10/22/10 - On 10/15/10, the Department received a Groundwater Monitoring Report & Remedial Action Plan, dated 10/12/10. It is

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

currently under review. 12/28/10 - The Department submitted comments on the October 12, 2010 Remedial Action Plan to Cumberland Farms on December 1, 2010. 07/28/11 - The Department submitted comments on the June 27, 2011 Groundwater Monitoring Report to Cumberland Farms on July 27, 2011. 03/26/12 - The Department received the February 29, 2012 Groundwater Monitoring Report on March 2, 2012. It is currently under review. 04/24/12 - The Department submitted comments on the February 29, 2012 Groundwater Monitoring Report to Cumberland Farms on April 16, 2012. 10/25/12 - The Department received the September 24, 2012 Groundwater Monitoring Report on September 26, 2012. It is currently under review. 11/27/12 - The Department submitted comments on the September 2012 Groundwater Monitoring Report to Cumberland Farms on November 5, 2012. 04/25/13 - The Department submitted comments on March 2013 semi-annual Groundwater Monitoring Report to Cumberland Farms on April 3, 2013. Quarterly groundwater monitoring of monitoring well MW-6 will continue for two additional quarters, i.e. 1st and 2nd quarters of 2013. 09/25/13 - The Department submitted comments on the September 2013 Groundwater Monitoring Report to Cumberland Farms on September 11, 2013. Quarterly monitoring of monitoring well MW-6 will continue for two additional quarters, i.e. the 3rd and 4th quarters of 2013. 04/25/14: The Department received a Spill Closure Request for this Spills site on 3/31/14. The Spill was closed on 4/25/14 based on the Department's review of the Spill Closure Request report."

Remarks:

"soil tested positive."

All Materials:

Site ID: 297827  
Operable Unit ID: 855619  
Operable Unit: 01  
Material ID: 518711  
Material Code: 0009  
Material Name: gasoline  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: .00  
Units: G  
Recovered: .00  
Oxygenate: Not reported

NY MANIFEST:

Name: EXXON COMPANY USA  
Address: 8779 BAY PARKWAY  
City,State,Zip: BROOKLYN, NY 11214  
Country: USA  
EPA ID: NYD986949030  
Facility Status: Not reported  
Location Address 1: 8775 BAY PKWY STA 3-7337  
Code: BP  
Location Address 2: Not reported  
Total Tanks: Not reported  
Location City: BROOKLYN  
Location State: NY  
Location Zip: 11201  
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYD986949030  
Mailing Name: EXXON COMPANY USA

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Mailing Contact: CHRISTINE SULLIVAN  
Mailing Address 1: PO BOX 2180  
Mailing Address 2: Not reported  
Mailing City: HOUSTON  
Mailing State: TX  
Mailing Zip: 11252  
Mailing Zip 4: Not reported  
Mailing Country: USA  
Mailing Phone: 7136567709

NY MANIFEST:

Document ID: CTF1157362  
Manifest Status: Not reported  
seq: 01  
Year: 2003  
Trans1 State ID: CA016  
Trans2 State ID: Not reported  
Generator Ship Date: 11/05/2003  
Trans1 Recv Date: 11/05/2003  
Trans2 Recv Date: Not reported  
TSD Site Recv Date: 11/12/2003  
Part A Recv Date: Not reported  
Part B Recv Date: Not reported  
Generator EPA ID: NYD986949030  
Trans1 EPA ID: CAR000118992  
Trans2 EPA ID: Not reported  
TSDF ID 1: CTD002593887  
TSDF ID 2: Not reported  
Manifest Tracking Number: Not reported  
Import Indicator: Not reported  
Export Indicator: Not reported  
Discr Quantity Indicator: Not reported  
Discr Type Indicator: Not reported  
Discr Residue Indicator: Not reported  
Discr Partial Reject Indicator: Not reported  
Discr Full Reject Indicator: Not reported  
Manifest Ref Number: Not reported  
Alt Facility RCRA ID: Not reported  
Alt Facility Sign Date: Not reported  
MGMT Method Type Code: Not reported  
Waste Code: D001 - NON-LISTED IGNITABLE WASTES  
Waste Code: Not reported  
Waste Code: Not reported  
Waste Code: Not reported  
Waste Code: Not reported  
Waste Code: Not reported  
Quantity: 00200  
Units: G - Gallons (liquids only)\* (8.3 pounds)  
Number of Containers: 001  
Container Type: TP - Tanks, portable  
Handling Method: T Chemical, physical, or biological treatment.  
Specific Gravity: 01.00